

FIG. 1

Prior art




Figure 2 Prior art




Figure 3 (prior art)

Borehole Size Correction for an HDLL lateral subarray

K = 53.883; Tool Centered




Figure 4 (prior art)




Figure 5a (prior art)




Figure 5b




Figure 6




Figure 7